



Prepared by:  
Mighty Holdings Inc  
100 S Commons  
Pittsburgh, PA 15212

Prepared for:  
Susie Q Realty  
307 Realty Street  
Rochester, NY 14602

## Mighty Inspection Report Estimate

Item description	Page on report	Estimated Cost
Sill plate - seal gaps around the perimeter to prevent wood damage	4	\$400.00
Siding nails - secure nail pops and seal where needed	5	\$130.00
Roof - secure loose nail pops and seal	8-9	\$280.00
Downspout - secure transition piece	10	\$40.00
Yard Drain - Replace access cap	15	\$110.00
HVAC - general service	14	\$185.00
Garage Door, Main - replace seal	19	\$160.00
Master Bath - Seal noted gaps.	21	\$140.00
<b>Total Estimated Cost</b>		<b>\$1445.00</b>

Mighty's estimates are proudly backed by our contracting partners and regionally-based.

**Thank you for choosing Mighty!**

If you have any questions about this invoice or would like to amend your request, please email us at [estimates@mightyhomeapp.com](mailto:estimates@mightyhomeapp.com).